


FS 1 – Sanitizer solutions are not of adequate strength (bucket #3)




FS 1 – Sanitizer solutions are not of adequate strength (Coolatta Cup sanitizer)








adequate strength. Sink sanitier is too measure the sanitizer and volume of FS 1 – Sanitizer solutions are not of strong. It is twice the allowable limit. Manager indicated they do not water necessary for proper concentration




FS 13 – Areas where no cleaning has taken place allowing for harborage of pests like fruit flies, house flies and roaches

FS 13 – Areas where no cleaning has taken place allowing for harborage of pests like fruit flies, house flies and roaches





FS 15 – Ceilings and walls in the basement are not properly maintained. Visible cracks and peeling plaster and paint were observed.




FS 13 – Areas where no cleaning has taken place allowing for harborage of pests like fruit flies, house flies and roaches

space allowed to ensure proper cleaning











FS 15 – Food is being stored directly on the floor. Observed drinks on the floor for nearly 2 hours during the inspection. Requested the drinks be stored properly but the manager did not comply as he was only 1 of 2 in the store at the time

FS 15 – Supplies being stored directly on the floor.







thereby not providing proper protection FS 17 & FS 15 - Muffins are not dated and plastic overwrap is opened from contamination